

# Precipitation Rate of Zirconia (Volumetric Method)




FIG. 1




FIG. 2

Precipitation Rate of Zirconia in Acetone  
KR 41B at Varying Concentrations  
(Mass Accumulation Method)




FIG. 3